

**MS Word Export To Multiple PDF Files Software - Please purchase
license. SECTION 1
1.2 Results Summary
Art and Education**

ACM SURVEY RESULTS

The following homogeneous building material types were sampled as part of this survey conducted May 20-21, 2003. Results are summarized in the table below:

1st Floor

| MTL # | MATERIAL DESCRIPTION | LOCATION | F/NF ¹ | COND. ² | % ACM | # SAMP. | QUANTITY |
|-------|------------------------------------|--|-------------------|--------------------|--------------------------------|---------|-----------|
| 01 | Drywall (white) Joint compound* | SE entry, 107a, 108, 109, 109a, 111, 111c, 114, 118, 121, 127, 127a, 127b, 143a, 145, 160a, 160b, 160c, 168, 168a, 169, 175, 175a, 176, 183, 186, 191, 192, 194, 1206, 1206a, 1206b, 1207, 1211, 1211a, 1231, 1231b, 1232, 1233, 1233a, 1233b, 1233c | F | Good | Drywall = ND JC = ND | 3 | N/A |
| 02 | 9" x 9" Gray floor tile/ mastic | Hallways, 193, 192, 186, 191, 183, 177, 175a, 175, 160a, 160b, 160c, 1206b, 1233, 1233b, 1233c, 1232, 1215, 1215a, 1211, 1211a, 1207, 106, 118, 120, 127, 127a, 127b, 140, 143a, 153, 145, 142a, 142b | NF | Good | Floor tile = 5% Mastic = 5% | 3 | 14,000 SF |
| 03 | Pink sink under coating | All floors: 168a, 160c, 1206, 1227, 250a, 239a, 268, 278, 286, 385 | NF | Good | 4% | 3 | 40 SF |

| | | | | | |
|----|--------------------------|---|----|------|----------------|
| 37 | Tan cove base/ mastic | Hallway, 246, 246a, 239, 239a and b, 238, 225, 209, 210, 211, 213, 214, 214a, 215, 217, 219, 221, 223, 207, 208, 205, 203, 210, 206, 271, 268, 285, 286, 290 | NF | Good | Cove base = ND |
|----|--------------------------|---|----|------|----------------|

| | | | | | | | |
|----|--|---|----|------|--------------------------|---|-----------|
| 62 | Drywall (orange) Joint compound* | 373e | F | Good | Drywall = ND JC = <1% | 3 | 500 SF |
| 63 | Drywall (white) Joint compound* | All rooms except hallways, 392, 392a, b, c, d, e, 373e, 369, 369a, b, WRR, MRR, 311, shops, elevator | F | Good | Drywall = ND JC = <1% | 3 | 20,000 SF |
| 64 | 1' x 1' White fissure ceiling panel | 384, 384a, 382, 382a, 378, 368a, b, c, 368, 366, 366a, 307, 309, 311, 313, 315, 317 | F | Good | ND | 3 | N/A |
| 65 | Brown mastic behind ceiling panel | Same as above (MTL #64) | NF | Good | ND | 3 | N/A |
| 66 | Drywall (blue) Joint compound* | 392, 392a thru e | F | Good | Drywall = ND JC = <1% | 3 | 3,500 SF |
| 67 | 2' x 2' White fissure ceiling panel | 392, 392c | F | Good | ND | 3 | N/A |