

Concord Campus

ACM SURVEY RESULTS

The following homogeneous building material types were sampled as part of this survey conducted in 1994. Results are summarized in the table below:

MTL #	MATERIAL DESCRIPTION	LOCATION	F/NF ¹	COND. ²	% ACM	# SAMP.	QUANTITY
	Pipe Hangers	Academic Services Building	NF	Good	25 %	N/A	N/A

* Reviewed Jan. 2009- location of hangers were re-sampled and only identified one building to contain asbestos(not throughout campus as previously reported).

¹ F = Friable; NF = Non-friable Friability is further defined in section 4.

² Cond. = Condition Of Materials Either good, fair or poor.

* Bay Area Air Quality Management District – identifies this material as friable for renovation and disposal purposes.

ND = None Detected

N/A = Not Applicable

SF = Square Feet